



Legend

- Monitoring Point A - G
- Trench Well 1, 3, 7, and 11
- ▲ Deep vapor Monitoring Points: 1 - 12
- ▲ Shallow Vapor Monitoring Points: 21-41
- Vapor Extraction Well
- NR Data Not Recorded
- Debris/Fill Footprint
- - - Perimeter Fence
- ▬ Methane Extraction Trench

RESULTS ARE IN PARTS PER MILLION BY VOLUME (PPMV)



FIGURE 1

Site Layout
& Last 4 Methane Readings
Week Beginning
10 January 2011
Manor View Dump Site
Fort George G. Meade, MD



1114 Benfield Boulevard, Suite A
Millersville, Maryland 21108
Tel (410) 987-0032 Fax (410) 987-4392